


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- Insert cable/wire into solder cup.
  Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT-OUT



-	GmbH	DO NOT ALTER CAD DRAWING BY HAND					tolerance			scale: 5:1	
A DU									1 7 1	material: see sheet 1	
DRAWING MAY NOT BE COPIED OR CODICED IN ANY WAY, AND MAY NOT ASSED ON TO A THIRD PARTY WITHOUT THEN DEPARCEION	CONEC								dim. in mm		
	FC							date	name	title:	
	SION. COPYRIGHT OF						drawn	24.10.12	Schmidt	PANEL CUT-OUT	
	ÆIG						appd.	25.10.12	Fischer	D-SUB COMBINATION FEMALE 3W3CS	;
	TOP						norm			Solder cup; with hexlocking screw	
	0) -						d-old			dwg no: DIN-	N-
								45 =		15K1A428	3
	TEN		а	Original						sh:	2
THIS REPR BE PA	WRITTEN PE OWNERSHIP		rev.	description	date	name	4	7/1		part no: see sheet 1	