


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Signal Contact
- 3.1. Operate the soldering iron at 350℃, 50 Watt m ax. and use a pencil tip.
- 3.2. Apply some solder to the solder tip of the soldering iron
- 3.3. Put tip to wire in solder cup.
- 3.4. After 1 second bring in solder.
- 3.5. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 4. Power Contact
- 4.1. Operate the soldering iron at 350℃, 100 Watt max. and use a pencil tip.
- 4.2. Apply some solder to the solder tip of the soldering iron
- 4.3. Put tip to wire in solder cup.
- 4.4. After 1 second bring in solder.
- 4.5. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 5. Remove soldering iron.
- 6. Wait until solder gets rigid again.
- 7. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT-OUT



_											
DRAWING MAY NOT BE COPIED OR	-	GmbH	HAND					tolerance			scale: 3:1
	D OR AY NOT WITHOU	5									material: SEE SHEET 1
	0 Z E	CONEC	B√				dim. in mm				
	PIED MAY TY W	9	9						date	name	title:
	E COPIE AND M/ PARTY	읽	DRAWING					drawn	20.11.15	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
	OT BI WAY, HIRD							appd.	20.11.15	Schmidt	D-SUB COMBINATION FEMALE 24W7S
	N A I	8	8					norm			Solder cup, with hexlocking screw
	₹ \$ C SS		Ĕ					d-old			dwg no: DIN
	WING CED I D ON PERM	4 H	AT T						45 =		15K1 \ 1 \ 1 \ 1 \ 1
		άI	N P	а	Original				?}		15K1A1818 sh: 2
	THIS REPR BE PA WRIT			rev.	description	date	name	4		71-6	part no: SEE SHEET 1

\_\_\_\_