


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
- 4. apply some solder to the solder tip of the soldering iron.
- 5. Put tip to wire in solder cup.
- 6. After 1 seconds bring in the solder
- 7. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 8. Remove soldering iron.
- 9. Wait until solder gets rigid again.
- 10. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT-OUT



	5	GmbH	HAND					tol	erance		scale: 5:1	]
	ED OR AY NOT WITHOU	WKITTEN PERMISSION. OWNERSHIP AND COPYRIGHT OF CONEC G	DO NOT ALTER CAD DRAWING BY H							dim. in mm	material: SEE SHEET 1	ı
	MAY MAY								date		title:	- ^  ^
	S P S							drawn	16.09.2015		RECOMMENDED PANEL CUT-OUT	
	NOT BE WAY, A I'HIRD F							appd.	23.09.2015	Fischer	D-SUB FEMALE HD 15pos. SOLDER CUP	ı
	> A A B							norm			with closed 4-40 UNC thread	ı
	G M A NI A TO							d-old			dwg no: DIN-	1
	WIN CED D O									15K1A1674 A3		
	DRA ODU ASSE			а	Original					15K1A1674 sh: 2	]	
	THIS REPR BE PA			rev.	description	date	name		<b>11-</b>	part no: SEE SHEET 1	1	