


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 °C, 100 Watt max. and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## RECOMMENDED PANEL CUT OUT



	r JUT GmbH	HAND					tolerance			scale: 3:1	
										material: SEE SHEET 1	
	E COPIED OR AND MAY NOT PARTY WITHOL HT OF CONEC G	DRAWING BY							dim. in mm		
I≡∑≻								date	name	title:	
							drawn	06.01.12	Henneboel	PANEL CUT-OUT	
							appd.	06.01.12	Fischer	D-SUB FEMALE 2W2CS SOLDER CUP	
	WING MAY CED IN AN D ON TO A PERMISSI IIP AND C	DO NOT ALTER CAD					norm			with threaded insert and hexlocking screw	
							d-old			dwg no: DIN-	N-
										15K1A989	(3
			а	Original						I SK I A 909	2
			rev.	description	date	name	•	7/1		part no: SEE SHEET 1	