


## Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350 ℃, 50 Watt max. and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

## **RECOMMENDED PANEL CUT-OUT**



	THIS DRAWING MAY NOT BE COPIED OR REPORTED IN ANY WAY, AND MAY NOT BE PASSED ON TO A THIRD PARTY WITHOUT WRITTEN PERMISSION.  WRITTEN PERMISSION.	ALTER CAD DRAWING BY HAND					tolerance		dim. in mm	scale: 3:1 material: SEE SHEET 1	]
								date	name	title:	
							drawn	15.03.11	Henneboel	RECOMMENDED PANEL CUT-OUT	
							appd.	15.03.11	Fischer	D-SUB HD FEMALE 78pos. SOLDER CUP	
							norm			with threaded lock and 4-40 UNC stud bolt	
							d-old			dwg no: DIN-	
							_	45 =		15K1A000 A3	ı
	S DRAW PRODUCI PASSED ITTEN P	NOT	а	Original						15K1A808 sh: 2/2	1
	THIS REPR BE PA WRIT OWNE	D0 N	rev.	description	date	name	7			part no: SEE SHEET 1	
			D		$\overline{\Lambda}$		C			В	-