


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Signal Contact
 - 3.1 Operate the soldering iron at 350°C, 50 Watt max. and use a pencil tip.
 - 3.2. Apply some solder to the solder tip of the soldering iron.
 - 3.3. Put tip to wire in solder cup.
 - 3.4. After 1 second bring in solder.
 - 3.5. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 4. Power Contact
 - 4.1 Operate the soldering iron at 350°C, 100 Watt max. and use a pencil tip.
 - 4.2. Apply some solder to the solder tip of the soldering iron.
 - 4.3. Put tip to wire in solder cup.
 - 4.4. After 1 second bring in solder.
 - 4.5. Heat for 5 seconds longer. Do not heat contact more than 6 seconds in total.
- 5. Remove soldering iron.
- 6. Wait until solder gets rigid again.
- 7. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



	r DUT GmbH	HAND					tol	erance		scale: 4:1
١	OR NOT THOUT									material: SEE SHEET 1
١		B√							dim. in mm	
١	COPIED (AND MAY PARTY WI	9						date	name	title:
١	AND MAPARTY PARTY HT OF C	DRAWING					drawn	16.09.15	Lehmenkühler	RECOMMENDED PANEL CUT-OUT
١	AY NOT BE ON WAY, ALL ATHIRD PASION.	TER CAD					appd.	21.09.15	Fischer	D-SUB COMBINATION MALE 7W2P SOLDER CUP
ı	AY NG ANY V SION COPY						norm			with open 4-40 UNC thread
Σ:	N S S S						d-old			dwg no: DIN-
	WINGED I							45 =		15K1A1667 Ash:
١	DRA ODU ASSE TEN ERSF		а	Original				? 2 1		
	THIS DRAWI REPRODUCE BE PASSED (WRITTEN PE OWNERSHIP		rev.	description	date	name	•		11.	part no: SEE SHEET 1