

# Set of electronic screwdrivers in carton box

607CS7E



## Profiles



## Product features

- 4x Flat electronic screwdriver (article 605E) dim. 0.3 x 1.8x60, 0.4 x 2.5x75, 0.5 x 3.0x100, 0.8 x 4.0x100
- 3x Crosstip (PH) electronic screwdriver (article 615E dim. PH 00x60, PH 0x60, PH 1x80)

| Product name                                 | SKU                                                                                 | Article | Dimensions                                                  | Quantity |
|----------------------------------------------|-------------------------------------------------------------------------------------|---------|-------------------------------------------------------------|----------|
| Set of electronic screwdrivers in carton box | 620960                                                                              | 607CS7E | -                                                           | 7        |
| Flat electronic screwdriver                  |  | 605E    | 0.3 x 1.8x60, 0.4 x 2.5x75,<br>0.5 x 3.0x100, 0.8 x 4.0x100 | 4        |
| Crosstip (PH) electronic screwdriver         |  | 615E    | PH 00x60, PH 0x60, PH 1x80                                  | 3        |

\* Images of products are symbolic. All dimensions are in mm, and weight in grams. All listed dimensions may vary in tolerance.

# Safety tips



- Use a screw holding screwdriver to get screws started in awkward, hard-to-reach areas.
- Use a stubby screwdriver in close quarters where a conventional screwdriver cannot be used.
- A rounded tip should be redressed with a file; make sure edges are straight.
- Screwdrivers used in the shop are best stored in a rack. This way, the proper selection of the right screwdriver can be quickly made.
- Keep the screwdriver handle clean; a greasy handle is apt to cause accidents.
- A screwdriver should never be used as pry bar. If it is overstressed in this manner, the blade might break and send a particle of steel into the operator's arm or even towards his eyes.



- Don't use pliers on the handle of a screwdriver to get extra turning power. A wrench should only be used on the square shank or bolster of a screwdriver that is especially designed for that purpose.
- Don't expose a screwdriver blade to excessive heat as it may reduce the hardness of the blade.
- Don't use a screwdriver with a split or broken handle.
- Don't use a regular screwdriver to check a storage battery or to determine if an electrical circuit is live.