


Mounting set for photoelectric sensors

MOUNTING SET OH



Operating conditions

Ambient temperature	[°C]	-30...60
---------------------	------	----------

Mechanical data

Weight	[g]	10.1
Materials		ABS

Remarks

Pack quantity		1 pcs.
---------------	--	--------